

Foreign Airworthiness Directives

Number: EASA 2017-0199

Subject: ATA 25 – EQUIPMENT & FURNISHING – OUTBOARD LOAD SYSTEM – INSPECTION / REPLACEMENT

Applicability: AIRBUS HELICOPTERS DEUTSCHLAND GmbH, EC135 and EC635 helicopters

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0199.pdf>

Number: BZ 2017-10-01

Subject: ATA 27- FLIGHT CONTROLS- CASTLE NUT ON THE AILERON, RUDDER AND ELEVATOR TRIM TAB (OR AUTOTAB) ATTACHMENT BOLTS.

Applicability: Embraer S.A. EMB-500, EMB-505 airplanes

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/BZ2017-10-01.pdf>

Number: EASA 2017-0198

Subject: ATA 73 – ENGINE FUEL AND CONTROL – ENGINE ELECTRONIC CONTROLLER FIREBOX ASSEMBLY – REPLACEMENT

Applicability: ROLLS-ROYCE DEUTSCHLAND Ltd & Co KG, BR700-710 engines

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0198.pdf>

Number: FAA 2017-20-09

Subject: ATA 72 - TURBINE ENGINE BYPASS SECTION, PREVENT FAILURE OF THE FAN OGV FRAME, ENGINE SEPARATION, AND LOSS OF THE AIRPLANE

Applicability: General Electric, Model CF34-8E turbofan engines

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-20-09.pdf>

Number: EASA 2017-0196

Subject: ATA 34 – NAVIGATION – TRAFFIC COLLISION AVOIDANCE SYSTEM PROCESSOR – MODIFICATION (SOFTWARE UPDATE) / REPLACEMENT

Applicability: Airbus, Model A318, A319, A321 & A340 aeroplanes with Honeywell TPA-100B traffic alert and collision avoidance system

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0196.pdf>

Number: FAA 2017-20-06

Subject: ATA 72 - TURBINE SECTION, LOSS OF POWER DUE TO FAILURE OF THE LPT2 BLADE

Applicability: Honeywell, Model AS907-1-1A turbofan engines

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-20-06.pdf>