

## **Foreign Airworthiness Directives**

**Number:** FAA 2017-19-26

**Subject:** ATA 53 - Fuselage - Upper Skin Panel at Chem-milled Step Above Lap Joint - Inspection / Modification / Repair

**Applicability:** Boeing B737-600, -700, -700C, -800 and -900 series airplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-19-26.pdf>

**Number:** EASA 2017-0192

**Subject:** ATA 25 - Equipment & Furnishings - Passenger Seats - Modification

**Applicability:** Recaro Aircraft Seating Model 3510A and 3510D seats - the affected seats are known to be installed on, but not limited to Airbus A318, A319 and A320 aeroplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0192.pdf>

**Number:** EASA 2017-0193

**Subject:** ATA 63 - Main Rotor Drive - Main Rotor Mast - Inspection

**Applicability:** Airbus Helicopters MBB-BK117 Helicopters

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0193.pdf>

**Number:** FAA 2017-20-01

**Subject:** ATA 72 - Turbine/Turboprop Engines - Turbofan disk - Replacement

**Applicability:** Honeywell TFE731-20 and TFE731-40 Turbofan Engines

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-20-01.pdf>

**Number:** FAA 2017-20-05

**Subject:** ATA 53 - Fuselage - Cracking of Chem-milled step at certain stringers

**Applicability:** Boeing, Model 757-200 and -300 series airplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-20-05.pdf>

**Number:** FAA 2017-20-08

**Subject:** ATA 49 - Airborne Auxiliary Power and ATA 53 - Fuselage - Enclosure (firewall) - Revised Operating Procedures

**Applicability:** Gulfstream, Model G-IV, GIV-X, GV, GV-SP and GVI airplanes

**Link:** <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-20-08.pdf>