

## **Foreign Airworthiness Directives**

**Number:** EASA 2018-0049

**Subject:** ATA 72 – ENGINE – INTERMEDIATE PRESSURE COMPRESSOR ROTOR SHAFT AND BALANCE WEIGHTS – INSPECTION / MODIFICATION

**Applicability:** ROLLS-ROYCE plc. RB211 Trent 700 engines

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2018-0049.pdf>

**Number:** EASA 2016-0167R1

**Subject:** ATA 25 – EQUIPMENT / FURNISHINGS – REAR CABIN ATTENDANT SEAT – INSPECTION / REPAIR

**Applicability:** Zodiac Seats France (formerly Sicma Aero Seat): CAS 536-series attendant seats Part Number (P/N) 53600, all dash numbers, all serial numbers

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0167r1.pdf>

**Number:** EASA 2017-0116R2

**Subject:** ATA 05 – MAIN GEARBOX MAGNETIC PLUGS – INSPECTION ATA 63 – MAIN ROTOR DRIVE - PLANET GEAR ASSEMBLIES – REPLACEMENT

**Applicability:** AIRBUS HELICOPTERS: SA 365 N, SA 365 N1, AS 365 N2, AS 365 N3 AND EC 155 B and EC 155 B1

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0116R2.pdf>

**Number:** FAA 2018-04-12

**Subject:** ATA 28 - FUEL - INSPECT FOR ELECTRICAL ARCING BETWEEN THE FUEL BOOST PUMP POWER CABLE WIRING AND THE SURROUNDING CONDUIT IN THE FUEL TANK AREA

**Applicability:** Boeing 737-100, -200, -200C, -300, -400, -500 series airplanes

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2018-04-12.pdf>