Transport Canada / Transports Canada
Civil Aviation / Aviation Civile

***** Le texte français suit l'anglais. *****

The following has recently been posted to the Transport Canada AD website:

Number: EU2019-0144
Subject: ATA 30 – ICE AND RAIN PROTECTION – TOTAL AIR TEMPERATURE PROBE HEATER / ELECTRICAL CIRCUIT – MODIFICATION AND AIRCRAFT FLIGHT MANUAL AMENDMENT
Applicability: P.180 Avanti and Avanti II aeroplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0144.PDF

Number: US2019-12-05
Subject: ATA 72 - REPLACEMENT OF HIGH PRESSURE TURBINE FRONT SEAL
Applicability: CFM CFM56-5B and CFM56-7B model turbofan engines
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-05.PDF

Number: US2019-11-02
Subject: ATA 53 - INSPECTION OF LEFT AND RIGHT SIDE UNDER-WING LONGERONS FOR CRACKING AND REPAIR OR REPLACEMENT
Applicability: The Boeing Company Model 777-200, -200LR, -300, -300ER, and 777F series airplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-11-02.PDF

Number: EU2019-0147
Subject: ATA 32 – LANDING GEAR – MAIN LANDING GEAR SLIDING TUBE – INSPECTION
Applicability: Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232 and A320-233 aeroplanes.
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0147.PDF

Number: EU2019-0149
Subject: ATA 71 – POWERPLANT – ENGINE MOUNTING RODS – REPLACEMENT
Applicability: LEONARDO S.p.A. Model AB139 and AW139 helicopters
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0149.PDF

Number: US2019-12-12
Subject: ATA - 53 - FUSELAGE - GROUND OPERATING LIMITATION
Applicability: Piper Aircraft, Inc., Model PA-46-600TP (M600) airplanes,
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-12.PDF

Number: US2019-12-13
Subject: ATA 27 - FLIGHT CONTROLS - FAILURE OF THE AILERON TRIM ACTUATOR ATTACHMENT LUG
Applicability: Boeing Company Model 757-200, -200PF, -200CB, and -300 series airplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-13.PDF

Number: EU2019-0151-E
Subject: EMERGENCY AD - ATA 32 – LANDING GEAR – MAIN LANDING GEAR SLIDING TUBES – INSPECTION

Applicability: Airbus A319-111, A319-112, A319-115, A319-131, A320-214 and A320-232 aeroplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0151-E.PDF

Number: BZ2019-05-02
Subject: ATA 05 - TIME LIMITS/MAINTENANCE CHECKS - INTRODUCTION OF NEW AND MODIFICATION OF EXISTING INSPECTION REQUIREMENTS
Applicability: Embraer S.A. ERJ 190 series airplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/BZ2019-05-02.PDF

Number: BZ2019-05-01
Subject: ATA 05 - TIME LIMITS/MAINTENANCE CHECKS - INTRODUCTION OF NEW AND MODIFICATION OF EXISTING INSPECTION REQUIREMENTS
Applicability: Embraer S.A. ERJ 170 series airplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/BZ2019-05-01.PDF

Number: EU2019-0155
Subject: ATA 52 – DOORS – PASSENGER / CREW / EMERGENCY EXIT DOOR GIRT BAR SLIDER MECHANISM – FUNCTIONAL CHECK / LUBRICATION
Applicability: AIRBUS A330 and A340 aeroplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0155.PDF

Number: EU2019-0153
Subject: ATA 05 – TIME LIMITS / MAINTENANCE CHECKS – AIRWORTHINESS LIMITATIONS SECTION CHAPTER 5-40 – AMENDMENT
Applicability: Dassault Aviation Mystère-Falcon 200 aeroplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0153.PDF

Number: EU2019-0154
Subject: ATA 05 – TIME LIMITS / MAINTENANCE CHECKS – AIRWORTHINESS LIMITATIONS SECTION CHAPTER 5-40 – AMENDMENT
Applicability: Dassault Aviation Falcon 2000EX aeroplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0154.PDF

Number: US2019-12-18
Subject: ATA 71 - POWER PLANT - ENGINE AIR INDUCTION HOSES - INSPECTION / REPLACEMENT
Applicability: Robinson Helicopter Company Model R44 II helicopters
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-18.PDF

Number: US2019-12-09
Subject: ATA 34 – NAVIGATION – FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 TRAFFIC COLLISION AVOIDANCE SYSTEM/RESOLUTION ADVISORY CONFLICT – OPERATING LIMITATIONS
Applicability: Rockwell Collins, Inc. Flight Display System Application FDSA-6500
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-09.PDF

Number: EU2018-0076R1
Subject: ATA 32 – LANDING GEAR – HYDRAULIC LINE T-UNION – REPLACEMENT
Applicability: FOKKER, Model F28 aeroplanes
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0076R1.PDF

Number: EU2019-0164
Subject: ATA 32 – LANDING GEAR – FREE FALL ACTUATORS – INSPECTION / REPLACEMENT
Applicability: Airbus A330 and A340 series aeroplanes.
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0164.PDF

Number: EU2019-0165-E
Subject: ATA 65 – TAIL ROTOR DRIVE – TAIL ROTOR GEARBOX – INSPECTION / REPLACEMENT
Applicability: Airbus Helicopters SA 365, AS 365 and EC 155 helicopters
Link: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0165-E.PDF

****
****

Les informations suivantes ont été récemment publiées sur le site Web des consignes de navigabilité de Transports Canada. Le sujet et l'applicabilité sont alimentés à partir du document original. Les informations provenant de sources étrangères ne sont pas soumises à la Loi sur les langues officielles, il n'y a donc pas de traduction disponible.

Numéro: EU2019-0144
Sujet: ATA 30 – ICE AND RAIN PROTECTION – TOTAL AIR TEMPERATURE PROBE HEATER / ELECTRICAL CIRCUIT – MODIFICATION AND AIRCRAFT FLIGHT MANUAL AMENDMENT
Applicabilité: P.180 Avanti and Avanti II aeroplanes
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0144.PDF

Numéro: US2019-12-05
Sujet: ATA 72 - REPLACEMENT OF HIGH PRESSURE TURBINE FRONT SEAL
Applicabilité: CFM CFM56-5B and CFM56-7B model turbofan engines:
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-05.PDF

Numéro: US2019-11-02
Sujet: ATA 53 - INSPECTION OF LEFT AND RIGHT SIDE UNDER-WING LONGERONS FOR CRACKING AND REPAIR OR REPLACEMENT
Applicabilité: The Boeing Company Model 777-200, -200LR, -300, -300ER, and 777F series airplanes,
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-11-02.PDF

Numéro: EU2019-0147
Sujet: ATA 32 – LANDING GEAR – MAIN LANDING GEAR SLIDING TUBE – INSPECTION
Applicabilité: Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232 and A320-233 aeroplanes.
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0147.PDF

Numéro: EU2019-0149
Sujet: ATA 71 – POWERPLANT – ENGINE MOUNTING RODS – REPLACEMENT
Applicabilité: LEONARDO S.p.A. Model AB139 and AW139 helicopters
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0149.PDF

Numéro: US2019-12-12
Sujet: ATA - 53 - FUSELAGE - GROUND OPERATING LIMITATION
Applicabilité: Piper Aircraft, Inc., Model PA-46-600TP (M600) airplanes,
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-12.PDF

Numéro: US2019-12-13
Sujet: ATA 27 - FLIGHT CONTROLS - FAILURE OF THE AILERON TRIM ACTUATOR ATTACHMENT LUG
Applicabilité: Boeing Company Model 757-200, -200PF, -200CB, and -300 series airplanes
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-13.PDF

Numéro: EU2019-0151-E
Sujet: EMERGENCY AD - ATA 32 – LANDING GEAR – MAIN LANDING GEAR SLIDING TUBES – INSPECTION
Applicabilité: Airbus A319-111, A319-112, A319-115, A319-131, A320-214 and A320-232 aeroplanes
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0151-E.PDF

Numéro: BZ2019-05-02
Sujet: ATA 05 - TIME LIMITS/MAINTENANCE CHECKS - INTRODUCTION OF NEW AND MODIFICATION OF EXISTING INSPECTION REQUIREMENTS
Applicabilité: Embraer S.A. ERJ 190 series airplanes
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/BZ2019-05-02.PDF

Numéro: BZ2019-05-01
Sujet: ATA 05 - TIME LIMITS/MAINTENANCE CHECKS - INTRODUCTION OF NEW AND MODIFICATION OF EXISTING INSPECTION REQUIREMENTS
Applicabilité: Embraer S.A. ERJ 170 series airplanes
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/BZ2019-05-01.PDF

Numéro: EU2019-0155
Sujet: ATA 52 – DOORS – PASSENGER / CREW / EMERGENCY EXIT DOOR GIRT BAR SLIDER MECHANISM – FUNCTIONAL CHECK / LUBRICATION
Applicabilité: AIRBUS A330 and A340 aeroplanes
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0155.PDF

Numéro: EU2019-0153
Sujet: ATA 05 – TIME LIMITS / MAINTENANCE CHECKS – AIRWORTHINESS LIMITATIONS SECTION CHAPTER 5-40 – AMENDMENT
Applicabilité: Dassault Aviation Mystère-Falcon 200 aeroplanes
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0153.PDF

Numéro: EU2019-0154
Sujet: ATA 05 – TIME LIMITS / MAINTENANCE CHECKS – AIRWORTHINESS LIMITATIONS SECTION CHAPTER 5-40 – AMENDMENT
Applicabilité: Dassault Aviation Falcon 2000EX aeroplanes
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0154.PDF

Numéro: US2019-12-18
Sujet: ATA 71 - POWER PLANT - ENGINE AIR INDUCTION HOSES - INSPECTION / REPLACEMENT

Applicabilité: Robinson Helicopter Company Model R44 II helicopters
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-18.PDF

Numéro: US2019-12-09
Sujet: ATA 34 – NAVIGATION – FLIGHT DISPLAY SYSTEM APPLICATION FDSA-6500 TRAFFIC COLLISION AVOIDANCE SYSTEM/RESOLUTION ADVISORY CONFLICT – OPERATING LIMITATIONS
Applicabilité: Rockwell Collins, Inc. Flight Display System Application FDSA-6500
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2019-12-09.PDF

Numéro: EU2018-0076R1
Sujet: ATA 32 – LANDING GEAR – HYDRAULIC LINE T-UNION – REPLACEMENT
Applicabilité: FOKKER, Model F28 aeroplanes
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0076R1.PDF

Numéro: EU2019-0164
Sujet: ATA 32 – LANDING GEAR – FREE FALL ACTUATORS – INSPECTION / REPLACEMENT
Applicabilité: Airbus A330 and A340 series aeroplanes.
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0164.PDF

Numéro: EU2019-0165-E
Sujet: ATA 65 – TAIL ROTOR DRIVE – TAIL ROTOR GEARBOX – INSPECTION / REPLACEMENT
Applicabilité: Airbus Helicopters SA 365, AS 365 and EC 155 helicopters
Lien: https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2019-0165-E.PDF