

**Transport Canada / Transports Canada
Civil Aviation / Aviation Civile**

The following has recently been posted to the [Transport Canada AD website](#):

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#). Le sujet et l'applicabilité sont alimentés à partir du document original. Les informations provenant de sources étrangères ne sont pas soumises à la Loi sur les langues officielles, il n'y a donc pas de traduction disponible.

Foreign Airworthiness Directive / Consignes de navigabilité étrangère

Number / Numéro: US 2016-25-12

Subject / Sujet : (ATA) of America Code 5510, Horizontal Stabilizer Structure.

Applicability / Applicabilité: M7 Aerospace LLC Models SA226-AT, SA226-T, SA226-T(B), SA226-TC, SA227-AC (C-26A), SA227-AT, SA227-BC (C-26A), SA227-CC, SA227-DC (C-26B), and SA227-TT airplanes, all serial numbers

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-25-12.pdf>

Number / Numéro: EU 2016-0241

Subject / Sujet : ATA 53 – Fuselage – Aft Cargo Door Lower Torsion Box Area – Inspection / Repair

Applicability / Applicabilité: Airbus A310 and A300-600 aeroplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0241.pdf>

Number / Numéro: US 2016-19-16

Subject / Sujet : Air Transport Association (ATA) of America Code 52, Doors.

Applicability / Applicabilité: The Boeing Company airplanes, Model 707-300, 707-300B, and 707-300C and Model 727C, 727-100C, and 727-200F series airplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-19-16.pdf>

Number / Numéro: EU 2016-0238

Subject / Sujet : ATA 53 – Fuselage – Door Stop Fitting Holes at Frames 66/68 – Inspection / Repair

Applicability / Applicabilité: A318, A319, A320 and A321 aeroplanes

Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0238.pdf>

Number / Numéro: EU 2016-0239

Subject / Sujet : ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitation Section

Applicability / Applicabilité: Airbus A318-111, A318-112, A318-121, A318-122, A319-111, A319-112, A319-113, A319-114, A319-115, A319-131, A319-132, A319-133, A320-211, A320-212, A320-214, A320-215, A320-216, A320-231, A320-232, A320-233, A320-251N, A320-271N, A321-111, A321-112, A321-131, A321-211, A321-212, A321-213, A321-231 and A321-232 aeroplanes, all manufacturer serial numbers.

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0239.pdf>

Number / Numéro: US 2016-24-09

Subject / Sujet : Air Transport Association (ATA) of America Code 27, Flight Controls.

Applicability / Applicabilité: Boeing Company Model 787-8 and 787-9

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-24-09.pdf>

Number / Numéro: EU 2015-0210R2

Subject / Sujet : HYDRAULIC POWER – PLATE ASSEMBLY ATTACHMENT POINTS – INSPECTION / CHECK

Applicability / Applicabilité: MBB-BK117 C-2, MBB-BK117 C-2e, MBB-BK117 D-2 and MBB-BK117 D-2m helicopters, all serial numbers.

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2015-0210R2.pdf>

Number / Numéro: EU 2016-0240

Subject / Sujet : ATA 53 – Fuselage – Tail Boom / Fenestron Junction Frame – Inspection

Applicability / Applicabilité: EC 130 B4 and EC 130 T2 helicopters, all serial numbers.

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0240.pdf>

Number / Numéro: US 2016-23-08

Subject / Sujet : ATA 53, Fuselage

Applicability / Applicabilité: Boeing Model 737-400 series airplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-23-08.pdf>

Number / Numéro: US 2016-23-02

Subject / Sujet : ATA 54, Nacelles/pylons

Applicability / Applicabilité: Boeing Model 777-200, -200LR, -300, -300ER, and 777F series airplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-23-02.pdf>

Number / Numéro: US 2016-23-10

Subject / Sujet : ATA 22, Autopilot System

Applicability / Applicabilité: Sikorsky Model S-76D helicopters

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-23-10.pdf>

Number / Numéro: EU 2016-0234

Subject / Sujet : ATA 33 – Lights – Passenger Reading Light / Circuit Breaker – Replacement

Applicability / Applicabilité: SAAB SF340A aeroplanes, serial numbers 004 to 138 inclusive, except those on which Saab (SB) 340-33-053 (modification/removal for cargo/freighter configuration) has been embodied.

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0234.pdf>

Number / Numéro: EU 2016-0156R1

Subject / Sujet : ATA 78 – ENGINE EXHAUST – EXHAUST PIPES – REPLACEMENT

Applicability / Applicabilité: Diamond DA 42 and DA 42 M

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0156R1.pdf>

Number / Numéro: EU 2016-0231

Subject / Sujet : ATA 57 – Wings – Inboard Flap Parts – Identification / Inspection

Applicability / Applicabilité: Airbus A330 and A340 aeroplanes, all serial numbers.

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0231.pdf>

Number / Numéro: US 2016-22-13

Subject / Sujet : ATA 53 - Inspection to detect and correct widespread cracking in the S-14L and S-14R lap splices that could result in reduced structural integrity of the airplane

Applicability / Applicabilité: Boeing 737-600, -700, -700C, -800, -900, and -900ER series airplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-22-13.pdf>

Number / Numéro: US 2016-22-17

Subject / Sujet : ATA 53 - Change the configuration of the grounding jumpers connecting the ECS brackets and CRN straps, including all applicable related investigative and corrective actions.

Applicability / Applicabilité: Boeing 787-8 airplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-22-17.pdf>

Number / Numéro: GY 2016-0265

Subject / Sujet : ATA 57 - Main Wing Spar fractures due to unknown cause requires grounding of all aircraft and performing AD requested tasks.

Applicability / Applicabilité: Fauvel AV-36 Models (AV-36, AV-36C, AV-36C1, AV-36CR)

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/GY2016-0265.pdf>

Number / Numéro: US 2016-22-04

Subject / Sujet : AWL Changes - Revision to the Airworthiness Limitations Section (ALS) of the Aircraft Maintenance Manual (AMM), Chapter 05-10-10, based on fatigue and damage tolerance testing, and updated analysis.

Applicability / Applicabilité: Gulfstream Aerospace Corporation Model GV airplanes, certificated in any category, serial numbers 501 through 693 inclusive and serial number 699; and Model GV-SP airplanes, certificated in any category, serial numbers 5001 through 5433 inclusive.

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-22-04.pdf>

Number / Numéro: EU 2016-0230

Subject / Sujet : ATA 20 – Standard Practices Airframe – Electrical Wiring – Inspection / Modification

Applicability / Applicabilité: Falcon 7X aeroplanes

Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0230.pdf>

Number / Numéro: US 2016-24-51

Subject / Sujet : ATA- 65- This Emergency AD requires before further flight inspection and removal of Tail Rotor Pitch Change Shaft assemblies as noted in AD.

Applicability / Applicabilité: Sikorsky Aircraft Corporation (Sikorsky) Model S-92A helicopters

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-24-51.pdf>

Number / Numéro: EU 2016-0229

Subject / Sujet : ATA 57 – Wing – Damage Limitations Changes in Structural Repair Manual – Inspection / Repair

Applicability / Applicabilité: Airbus A300, A310, A300-600 and A300-600 ST aeroplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0229.pdf>

Number / Numéro: US 2016-21-05

Subject / Sujet : ATA - 28 - Fuel Boost Pump.

Applicability / Applicabilité: Boeing 777-200, -200LR, -300, and -300ER series airplanes,

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2016-21-05.pdf>

Number / Numéro: EU 2016-0228

Subject / Sujet : ATA 32 – Landing Gear – Tail Wheel Mounting Bracket – Inspection / Repair

Applicability / Applicabilité: Grob G 109 and Grob 109B powered sailplanes

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0228.pdf>

Number / Numéro: EU 2016-0210

Subject / Sujet : ATA 25 – Equipment / Furnishings – Seat Energy Absorber Assembly – Replacement

Applicability / Applicabilité: Attendant Seats NG and Pilot Seats 120/335. These seats are known to be installed on, but not limited to, Leonardo (formerly Finmeccanica, AgustaWestland, Agusta) A109, AW109SP and AW169 helicopters.

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2016-0210.pdf>

Number / Numéro: SW HB-2016-007

Subject / Sujet : ATA 57 - Wings - Fuselage - Main Frame 3 - Wing to Fuselage Attachment Bolts - Inspection

Applicability / Applicabilité: Pilatus model P3-03 and P3-05 aircraft, all serial numbers

Link / Lien: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/SWHB-2016-007.pdf>
