

## **Canadian Airworthiness Directives**

**Number:** CF-2011-30R2

**Subject:** ATA 53 - Fuselage – Cracking on the Forward Face of the Rear Pressure Bulkhead Web

**Applicability:** Bombardier Inc. aeroplane model CL-600-2B19

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2011-30R2-E.pdf>

**Number:** CF-2014-45R3

**Subject:** ATA 54 - Nacelle – A-Frame Structure – Insufficient Fillet Radius and Fouling with Main Landing Gear Stabilizer Brace and the Electrical Wiring Harnesses

**Applicability:** Bombardier Inc. model DHC-8-400, -401 and -402 aeroplanes

**Link:** <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2014-45R3-E.pdf>