

Foreign Airworthiness Directive / Consignes de navigabilité étrangère

Number: FAA 2017-10-16

Subject: ATA 57 - Wings

Applicability: Boeing, Model 787-8 and 787-9

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-10-16.pdf>

Number: FAA 2017-10-20

Subject: ATA 53 - Fuselage

Applicability: Piper, Navajo Models PA-31, PA-31-300, and PA-31-325 and Chieftain/T-1020 Models PA-31-350 airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-10-20.pdf>

Number: FAA 2017-10-21

Subject: ATA 53 - Fuselage

Applicability: Boeing, Model 737-300, -400, and -500 series airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-10-21.pdf>

Number: FAA 2017-10-07

Subject: ATA 53 - Fuselage - detect and correct cracking in the aft fuselage skin along the longitudinal edges of the bonded skin doubler

Applicability: Boeing 737-400

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-10-07.pdf>

Number: FAA 2017-10-08

Subject: ATA 53 - Fuselage - detect and correct cracking in the aft fuselage skin along the longitudinal edges of the chem-milled pockets in the bonded skin doubler

Applicability: Boeing 737-300

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-10-08.pdf>

Number: FAA 2017-11-09

Subject: ATA 53 - Fuselage - detect and correct corrosion of the fuselage skin, which could result in reduced structural integrity of the airplane.

Applicability: Learjet 60

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-11-09.pdf>