

Foreign Airworthiness Directive

Number: EASA 2017-0102

Subject: ATA 73 – Engine Fuel & Control – High Pressure / Low Pressure Fuel Pump Metering Unit – Inspection / Replacement

Applicability: Safran Helicopter Engines, S.A. (formerly Turbomeca, S.A.) ARRIEL 2B, 2B1 and 2B1A engines

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0102.pdf>

Number: FAA 2017-11-05

Subject: ATA 72 - Turbine section - Cracks found in the HPT wheel during an inspection

Applicability: Rolls Royce (previously Allison) AE 3007C or C1 engines

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-11-05.pdf>

Number: EASA 2017-0104

Subject: ATA 05 – Time Limits / Maintenance Checks – Main Gearbox Magnetic Plugs – Inspection
ATA 63 – Main Rotor Drive – Planet Gear Assemblies – Replacement

Applicability: Airbus Helicopters SA 365, AS 365 and EC 155 helicopters

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0104.pdf>

Number: EASA 2017-0103

Subject: ATA 72 – Engine – Timing Chain – Replacement / Aircraft Flight Manual – Limitations Section – Amendment

Applicability: Austro Engine GmbH, model E4 engines

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0103.pdf>

Number: EASA 2017-0105

Subject: ATA 24 – Electrical Power – Alternating Current Emergency Generation – Flight Warning
Computer Software Update

Applicability: Airbus A330-201, A330-202, A330-203, A330-223, A330-223F, A330-243, A330-243F, A330-301, A330-302, A330-303, A330-321, A330-322, A330-323, A330-341, A330-342 and A330-343 aeroplanes, all manufacturer serial numbers.

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0105.pdf>