

Foreign Airworthiness Directive

Number: EASA 2017-0121

Subject: ATA 05 – Time Limits / Maintenance Checks – Airworthiness Limitation Section – Amendment / Implementation

Applicability: SAFRAN HELICOPTER ENGINES, ARRIEL 2C and 2S engines

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0121.pdf>

Number: EASA 2017-0122

Subject: ATA 57 – Wings – Lower Tee Fitting – Modification

Applicability: AIRBUS, A310 series aeroplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0122.pdf>

Number: FAA 2017-14-13

Subject: (ATA) 25, Equipment and Furnishings.

Applicability: The Boeing Company Model 737-600, -700, -700C, -800, -900, and -900ER series airplanes

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-14-13.pdf>

Number: EASA 2017-0123

Subject: ATA 52 – Doors – Crew / Passenger Door – Inspection / Adjustment / Operational Test

Applicability: DASSAULT AVIATION, Mystère-Falcon 200, Mystère-Falcon 20-(x)5 and Mystère-Falcon 50 aeroplanes.

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0123.pdf>

Number: FAA 2017-15-02

Subject: ATA 79 ENGINE OIL SYSTEM AND ATA 28 AIRCRAFT FUEL SYSTEM

Applicability: BELL MODEL 212 AND 412 HELICOPTERS

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/US2017-15-02.pdf>

Number: EASA 2017-0124

Subject: ATA 05 - Time Limits / Maintenance checks - Airworthiness Limitations Section - Amendment / Implementation

Applicability: Leonardo S.p.A AB139 and AW139 helicopters

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0124.pdf>

Number: EASA 2017-0125

Subject: ATA 65 - Tail Rotor - Pitch Control Rod Bearing - Inspection / Replacement

Applicability: Airbus Helicopters SA365, AS 365, SA366 and EC 155 helicopters

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/EU2017-0125.pdf>