

**Transport Canada / Transports Canada
Civil Aviation / Aviation Civile**

**** Le texte français suit l'anglais. ****

The following has recently been posted to the [Transport Canada AD website](#):

Number: EU2018-0212

Subject: **ATA 71 – POWERPLANT – CFM56-5A ENGINE MOUNT TITANIUM CROSSBEAM – REPLACEMENT [LIFE LIMITATION]**

Applicability: AIRBUS, A319 and A320 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0212.PDF>

Number: US2018-20-05

Subject: **ATA 53 - CRACKING IN BULKHEAD FRAME WEB STATION 259.5**

Applicability: Boeing Model 727C, 727-100, 727-100C, 727-200, and 727-200F series airplanes.

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-20-05.PDF>

Number: US2018-20-04

Subject: **ATA 27 - FLIGHT CONTROLS, FLIGHT MANUAL SUPPLEMENT REVISION**

Applicability: Gulfstream Aerospace Corporation Model GVI airplanes.

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-20-04.PDF>

Number: EU2018-0211

Subject: **ATA 72 – ENGINE – FAN BLADES – INSPECTION**

Applicability: CFM INTERNATIONAL S.A., CFM56-7B engines

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0211.PDF>

Number: US2018-19-20

Subject: **ATA 53 - FUSELAGE - FATIGUE CRACKING OF CERTAIN FUSELAGE FRAMES AND STUB BEAMS**

Applicability: Boeing Model 737-200, -300, -400, and -500 series airplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-19-20.PDF>

Number: US2018-19-09

Subject: **ATA 32 - MAIN LANDING GEAR AND NOSE LANDING GEAR - FATIGUE FAILURE LANDING GEAR COMPONENTS**

Applicability: Sikorsky Model S-92A helicopters

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-19-09.PDF>

Number: EU2018-0202R1

Subject: **ATA 72 – ENGINE – LOW PRESSURE COMPRESSOR BLADES – INSPECTION**

Applicability: Rolls-Royce RB211-535E4 series engines

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0202R1.PDF>

Number: EU2016-0105R1

Subject: **ATA 53 – FUSELAGE – CABIN FLOOR BEAM JUNCTION – INSPECTION**

Applicability: Airbus A321 aeroplanes

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2016-0105R1.PDF>

Number: EU2018-0210-E

Subject: ATA 25 – EQUIPMENT & FURNISHINGS – HOIST CARRIER ASSEMBLY – INSPECTION

Applicability: AIRBUS HELICOPTERS DEUTSCHLAND GmbH, EC135 and EC635 helicopters

Link: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0210-E.PDF>

You are receiving this notification as a subscriber to the Transport Canada Civil Aviation e-Bulletin alert service. To unsubscribe, please use the form available on this Web page:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/menu-1152.htm>

For further information on **e-Bulletin**, you may wish to visit:

<http://www.tc.gc.ca/eng/civilaviation/opssvs/managementservices-referencecentre-menu-113.htm> . You

can also contact Transport Canada's Civil Aviation Communications Centre at 1-800-305-2059 or at

services@tc.gc.ca for questions regarding this service.

Les informations suivantes ont été récemment publiées sur le [site Web des consignes de navigabilité de Transports Canada](#). Le sujet et l'applicabilité sont alimentés à partir du document original. Les informations provenant de sources étrangères ne sont pas soumises à la Loi sur les langues officielles, il n'y a donc pas de traduction disponible.

Numéro: EU2018-0212

Sujet: ATA 71 – POWERPLANT – CFM56-5A ENGINE MOUNT TITANIUM CROSSBEAM – REPLACEMENT [LIFE LIMITATION]

Applicabilité: AIRBUS, A319 and A320 aeroplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0212.PDF>

Numéro: US2018-20-05

Sujet: ATA 53 - CRACKING IN BULKHEAD FRAME WEB STATION 259.5

Applicabilité: Boeing Model 727C, 727-100, 727-100C, 727-200, and 727-200F series airplanes.

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-20-05.PDF>

Numéro: US2018-20-04

Sujet: ATA 27 - FLIGHT CONTROLS, FLIGHT MANUAL SUPPLEMENT REVISION

Applicabilité: Gulfstream Aerospace Corporation Model GVI airplanes.

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-20-04.PDF>

Numéro: EU2018-0211

Sujet: ATA 72 – ENGINE – FAN BLADES – INSPECTION

Applicabilité: CFM INTERNATIONAL S.A., CFM56-7B engines

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0211.PDF>

Numéro: US2018-19-20

Sujet: ATA 53 - FUSELAGE - FATIGUE CRACKING OF CERTAIN FUSELAGE FRAMES AND STUB BEAMS

Applicabilité: Boeing Model 737-200, -300, -400, and -500 series airplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-19-20.PDF>

Numéro: US2018-19-09

Sujet: ATA 32 - MAIN LANDING GEAR AND NOSE LANDING GEAR - FATIGUE FAILURE LANDING GEAR COMPONENTS

Applicabilité: Sikorsky Model S-92A helicopters

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/US2018-19-09.PDF>

Numéro: EU2018-0202R1

Sujet: ATA 72 – ENGINE – LOW PRESSURE COMPRESSOR BLADES – INSPECTION

Applicabilité: Rolls-Royce RB211-535E4 series engines

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0202R1.PDF>

Numéro: EU2016-0105R1

Sujet: ATA 53 – FUSELAGE – CABIN FLOOR BEAM JUNCTION – INSPECTION

Applicabilité: Airbus A321 aeroplanes

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2016-0105R1.PDF>

Numéro: EU2018-0210-E

Sujet: ATA 25 – EQUIPMENT & FURNISHINGS – HOIST CARRIER ASSEMBLY – INSPECTION

Applicabilité: AIRBUS HELICOPTERS DEUTSCHLAND GmbH, EC135 and EC635 helicopters

Lien: <https://wwwapps.tc.gc.ca/saf-sec-sur/2/awd-cn/documents/EU2018-0210-E.PDF>