

Canadian Airworthiness Directives

Number: CF-2017-32

Subject: Flight Controls – Elevator Control System Bracket Cracking

Applicability: Bombardier Inc. model BD-700-1A10 and model BD-700-1A11 aeroplanes, serial numbers 9492 through 9711, 9713 through 9717, 9719 through 9726, 9728, 9730, 9732, 9733, 9743, and 9751.

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2017-32-E.pdf>

Number: CF-2017-33

Subject: Airframe – Corrosion

Applicability: Viking Air Ltd. (formerly Bombardier Inc.) model DHC-2 Mk. I, DHC-2 Mk. II and DHC-2 Mk. III aeroplanes, all serial numbers.

Link: <http://wwwapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2017-33-E.pdf>