

Canadian Airworthiness Directives

Number: CF-2018-19

Subject: SPECIAL CHECK OF ATTACHMENT FITTINGS – WING BOX MAIN LANDING GEAR SIDE BRACE FITTINGS

Applicability: Bombardier Inc. model CL-600-2A12 aeroplanes, serial numbers (S/N) 3001 through 3009 and 3011 through 3029.

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2018-19-E.pdf>

Number: CF-2016-14R1

Subject: ATA 53 - FUSELAGE – EXCESSIVE TAPE ON FLOOR STRUCTURE

Applicability: Bombardier Inc. aeroplanes: Model CL-600-2C10, CL-600-2D15, CL-600-2D24, and CL-600-2E25.

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2016-14R1-E.pdf>

Number: CF-2018-20

Subject: LANDING GEAR – MAIN LANDING GEAR SIDE BRACE ACTUATORS CONTAIN NON-CONFORMING SPLIT BALL BEARING

Applicability: Bombardier Inc. model BD-100-1A10 aeroplanes, serial numbers 20003 through 20500 and 20501 through 20665, equipped with split ball bearing part number 104467672.

Link: <http://www.wapps3.tc.gc.ca/Saf-Sec-Sur/2/AWD-CN/documents/CF-2018-20-E.pdf>